Southea
NITY COLLEGE

- - FIRST DAY OF CLASS - -

- Safety Glasses (Min. Z-87 Rated)
- Leather Safety-Toe Boots
- Hearing Protection (Ear Plugs)
- Flashlight
- Pocket Screwdriver
- Inspection Mirror
- Telescoping Magnetic Pickup Tool
- 4-Piece Pick Set
- Rubber Tip Air Nozzle
- Tire Pressure Gauge (At Least 120 Psi)
- Tire In f ator Air Chuck
- Tire Valve Core Tool
- Fluke 87 Multimeter
- 12v Test Light
- Wire Crimper/Stripper
- Coolant Tester
- Battery Terminal Cleaner
- Electrial Terminal Removal Tool
- Tool Bag

- - FIRST DAY OF WELDING CLASS - -

- Auto Darkening Welding Helmet W/ Ability For Shade Setting 5 or Separate Shade 5 Grinding Shield
- Long Sleeve Welding Jacket
- Denim or Cotton Jeans With No Holes
- Welding Gloves
- Welper (Welding) Pliers
- Slip Joint Pliers

- - THESE TOOLS WILL BE NEEDED IN ADDITION TO THE FIRST SEMESTER REQUIRED TOOLS. - -

TOOL BOX

- 1 - Roll-A-Way Tool Box (Top Chest Optional) (Maximum 55” long — 55” includes Ş = D = PLIERS